



05 - 2010  
310138-6X  
Repair Kit For Blade Clamp

\*Diagram is not available

Item No.	Type	Sub	Part No.	Description	Qty	Unit
1			310138-6	CLAMP	1	PC.
2			216002-8	BALL 4.8	1	PC.
3			256454-1	PIN 5.5-6	1	PC.
4			266272-9	TORX S.H. BOLT M5X10	1	PC.
5			323916-5	PUSH PIN	1	PC.
6			233018-8	COMPRESSION SPRING 3	1	PC.
7			162215-8	PUSH BUTTON	1	PC.
8			233247-3	COMPRESSION SPRING 16	1	PC.
9			267758-6	SPRING WASHER	1	PC.