



3 H.P. PLUNGE ROUTER (With Brake) Model 3612(MCA)



SERVICE CHANGES


(MCA Products only)

1. Change on Motor Bracket Com. and Bearing Retainer.



Item No.	Description	Type 1	Type 2
13	Bearing Retainer 50	285657-0	
		4 Holes	2 Holes
33	(+) C.S.H. Screw M4x14	251295-0	
		4 pieces	2 pieces
	Serial No.	N/A	N/A

2. Change on Knob, Compression Spring 12, Nut & Flat Washer.



Item No.	Description	Type 1	Type 2
68	Knob 50/Knob 50 Com.	271299-6 (No Longer Available)	152566-7 With Rubber Pin 4 (263002-9)
69	Compression Spring 12	231231-2	-----
70	Nut	252203-4 M10-15	410129-8 M10
71	Flat Washer 10	941251-5	-----

Above parts are completely interchangeable as a set.