





**SERVICE CHANGES**

**1. Change on Switch and Handle Set**


Left Side of Housing Set



Current Rib



New Rib



The Rib encircled by the broken line has been shortened in height

Item No.	Description	Type 1	Type 2
50	Handle Set	182724-1	
		Higher Rib Height	Lower Rib Height
54	Switch	651935-4	<b>651987-5</b>

Above parts are completely interchangeable as a set.

When installing the Type 2 Switch on the current Left Handle, be sure to cut the rib by 7.0 to 8.0mm.