



URGENT SAFETY RECALL



Do you own this product?

DGP180 18V LXT Grease Gun

The DGP180 Grease Gun was sold in the Canadian market under several different Makita model numbers. The affected tool models include all serial numbers between 11291 and 221391.

List of affected Makita Products:

DGP180Z - 18V LXT Grease Gun, Tool Only

DGP180SYX1 - 18V LXT Grease Gun, Compact x1Kit

DGP180YEX1 - 18V LXT Grease Gun, Compact x2Kit


DLX2465TX1 - 18V LXT 2 Tool Combo Kit, 5.0Ah x2

Affected Flexible Hoses:

191W58-9 - 1,200 mm Flexible Hose

191A80-4 - 600 mm Flexible Hose

191W59-7 - 600 mm Flexible Hose



STOP USING IMMEDIATELY

If purchased before March 1, 2025



Why the product is recalled: Repeated bending of the hose tip can cause a hole to form, which can cause the hose to burst.

Hazard: Risk of serious injuries including lacerations if the hose bursts during use.



1. Consumers should **STOP USING** the Grease Gun immediately.
2. Consumers should **REMOVE THE BATTERY** from the gun and any grease from the barrel.
3. Makita Canada will arrange for your Grease Gun to be **FITTED WITH A NEW HOSE**.
4. Find your Grease Gun **RECALL INTAKE FORM** by choosing one of the following:

Go to
makita.ca >
Safety Recall

OR



OR

Contact your nearest Makita Factory Service Centre

Richmond / Vancouver 1 800 663-0909	Quebec City / Les Saules 1 800 663-5757	Montreal / St. Leonard 1 800 361-7049
Saskatoon 1 888 931-0111	Edmonton 1 888 455-6644	Whitby / Toronto 1 800 263-3734

For Canadian product recall information please visit:

<https://recalls-rappels.canada.ca/en/alert-recall/makita-18v-cordless-grease-gun-and-certain-makita-flexible-hoses-recalled-due>